



COMMUTATOR SEGMENTS  
SHOULD LINE UP WITH  
COILS

NOTE: ALL COILS WOUND IN  
SAME DIRECTION!

F = FINISH (OF WINDING)  
S = START